

Inford 007/033

Michael O. Leavitt Governor Kathleen Clarke Executive Director Lowell P. Braxton Division Director 1594 West North Temple, Suite 1210 PO Box 145801 Salt Lake City, Utah 84114-5801 801-538-5340 801-359-3940 (Fax) 801-538-7223 (TDD)

August 25, 2000

TO:

Internal File

THRU:

Daron R. Haddock, Permit Supervisor

FROM:

James D. Smith, Senior Reclamation Specialist JDS

RE:

1999 Fourth Quarter Water Monitoring, Andalex Resources, Inc., Wildcat

Loadout, ACT/007/033-WQ99-4

1. Were data submitted for all of the MRP required sites?

YES[X] NO[]

Identify sites not monitored and reason why, if known:

No flow at the four water-quality monitoring sites.

2. On what date does the MRP require a five-year resampling of baseline water data.

See Technical Directive 004 for baseline resampling requirements. Consider the five-year baseline resubmittal when responding to question one above. Indicate if the MRP does not have such a requirement.

Resampling Due Date

No commitment to analyze for baseline parameters every fifth year was found in the Wildcat water-monitoring plan (Chapter IV, Section K - 8).

3. Were all required parameters reported for each site?

YES[]

NO[X]

Comments, including identity of monitoring site:

No flow at the four water-quality monitoring sites.

4. Were irregularities found in the data?

YES[]

NO[X]

Comments, including identity of monitoring site:

No flow at the four water-quality monitoring sites.

ACT/007/033-WQ99-4 August 25, 2000 Page 2

5. Were DMR forms submitted for all required
--

1st month, YES[] NO[X]
2nd month, YES[] NO[X]
3rd month, YES[] NO[X]

Identify sites and months not monitored:

Instead of DMR reports, Andalex sent a latter to the Division of Water Quality stating that there was no discharge at the Wildcat Loadout during the fourth quarter 1999.

6. Were all required DMR parameters reported?

YES[] NO[X]

Comments, including identity of monitoring site:

No flow at the four UPDES monitoring sites.

7. Were irregularities found in the DMR data?

YES[] NO[X]

Comments, including identity of monitoring site:

No flow at the four UPDES monitoring sites.

8. Based on your review, what further actions, if any, do you recommend?

No flow at any monitoring site at the Wildcat Loadout in the Fourth Quarter 1999. No further action is recommended.

sm

O:\007033.WCL\Water Quality\WQ_99-4.wpd